

BLUETOOTH

Change of index on the Blue PUCK T EN12830

1. MAIN FEATURE & REASON FOR PRODUCT CHANGE:

Change of index on Blue PUCK T EN12830 to be in correlation with the indexes of the Bluetooth and casing range of product. No HW or FW change.

2. IDENTIFICATION

This new index is identified: **IDF25251x** instead IDF30241x

3. AFFECTED PRODUCTS

<i>PRODUCT END OF LIFE NAME</i>	<i>PRODUCT PREVIOUS REFERENCE</i>	<i>NEW PRODUCT REFERENCE</i>	<i>REMARKS</i>
STANDARD BLE RANGE			
Blue PUCK T EN12830	IDF30241D	IDF25251D	V300 firmware version
Blue PUCK T EN12830	IDF30241E	IDF25251E	V400 firmware version

4. SCHEDULE

This modification has immediate effect. Any order placed with the old index will be modified and will be the subject of an order acknowledgment with the new index.

Montpellier, January, 07th, 2022

Pierre BONZOM
CEO

